EXHIBIT "B"

Repair Order Detail - Internal Copy

RO Number: 606649

RO Status: CLOSED

Customer: WHEELER, JAMES ROBERT

Phone(s): Contact: (903)806-7523

Vehicle: 1GCPYBEK7MZ174386

Main: (903)806-7523

2021 SILV

Silver

Click to View Cust Copy

Cell: (903)806-7523

PSX 9943

Mileage: 48,846

Service advisor: 330 Tag number: T12211 9/27/21

Payment type: CASH

Promised time: 03:30 PM

Promised date: 11/18/2021

Waiter: No

Estimate: 0.00

Customer Comments: No

			.~~~~~~~~~~~	~~~~~~
Α	C/S LOUD RATTLE	-CLANKING SOUND FROM UI	NDER HOOD WHEN MC	TOR RUNNING
	4066750 WC4	CRANKSHAFT REPLACEMENT	31.10	4,079.39
	Tech(s): 20			
	12695573	1 F-COVER		305.56
	12697973	1 F-(S)CAMSH	AFT	649.09
	12698637	1 F-(S)CAMSH	AFT	141.47
	12663277	16 (S)ADJUSTE	R	60.16
	12691897	1 F-(S)ACTUAT		102.45
	12691898	1 (S)ACTUATO	R	98.32
	4070004	O (O)DOLT		70.70

12000211	10	(O)ADOOOTEIX	00.10
12691897	1	F-(S)ACTUATOR	102.45
12691898	1	(S)ACTUATOR	98.32
12706091	2	(S)BOLT	76.76
12702894	2	(S)MAGNET	67.94
11548469	8	F-(S)BOLT	29.60
12664179	1	F-(S)CRANKSHAFT	660.41
12663477	5	F-(S)BEARING	17.80
11547674	10	(S)BOLT	39.00
12693989	1	(S)SEAL	3.59
11548686	1	(S)BOLT	5.59

12707673	1 F-(S)HOUSING	54.61
11548178	10 (S)BOLT	33.60
11548183	5 (S)BOLT	18.80
12663348	1 (S)GASKET	25.08
12671643	1 F-(S)GUIDE	10.21
12671645	1 F-(S)GUIDE	7.68
12701225	16 F-/S)ΔRM	84 32

12/01223	10 1 -(3)ANN	04.32
12691233	1 F-(S)GASKET	35.78
11547740	10 F-(S)BOLT	37.60
11548183	3 (S)BOLT	11.28
12663797	1 F-(S)GUIDE	12.28
12663426	1 F-(S)GASKET	5.31

12698384	2 (S)GASKET	6.72
12666026	1 (S)SEAL	4.92
12665976	1 F-(S)GASKET	4.77
12665075	1 F-(S)GASKET	3 65

	a to the first term of the common of the com	0.00
12668035	1 F-(S)SEAL	3.56
12687166	1 GASKET	16.55
12687885	1 (S)GASKET	8.48
84941400	1 GASKET	5.44

11549150 2 (S)BOLT 7.50 11549086 2 STUD 12.06 9.34 2 (S)NUT 11588835 1 GASKET 3.53 12663529 12696999 1 GASKET 4.54

4.77 12663528 1 GASKET 1 GASKET 12667635 3.70 Page 1, Created: 02/23/2023 05:38:28 PM

Repair Order Detail - Internal Copy

RO Number: 606649

RO Status: CLOSED

Customer: WHEELER, JAMES ROBERT

Phone(s): Contact: (903)806-7523

Vehicle: 1GCPYBEK7MZ174386

Main: (903)806-7523 2021 SILV

Silver

Click to View Cust Copy

Cell: (903)806-7523

PSX 9943

Mileage: 48,846

Service advisor: 330 Tag number: T12211

12663473

12663474

12663475

Payment type: CASH Promised time: 03:30 PM

Promised date: 11/18/2021

Waiter: No

Estimate: 0.00

Customer Comments: No.

4.50

7.12

7.12

33.51

3.53

36.49

37.62

7,542.22

ray number. 112211	Tromised date. 11/10/2021 Customer C	omments. No
~~~~~~~~~~~~~~~~	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	~~~~~
12663312	1 (S)PIPE	47.25
12663540	4 (S)GASKET	17.40
12662045	1 (S)FOLLOWER	30.12
12667009	1 (S)SEAL	3.70
12700915	1 (S)SEAL KIT	122.12
12713653	1 (S)PAN	96.03
12692513	1 ČĹÍP	3.83
12691858	1 F-(S)TENSIONER	37.76
55495105	1 XPF66	7.37
12346290	2 COOLANT DEXCOOL CONC	40.44
19333512	1 THREAD SEALANT	21.87
88862587	1 CAM PRE-LUBE & LIFTER	26.74
12693566	1 F-(S)BEARING KIT	39.41
12693045	1 F-(S)PUMP	145.08

1 F-(S)BEARING

2 F-(S)BEARING

2 F-(S)BEARING

19369831 1 SEALANT 1 (S)SEAL 12689669 12716029 1 F-(S)COVER 19420057 6 0W20 DEX1 F/S GEN2

BULK JAM 4,079.39 Other: 0.00 Total Line A:

Pts: 3,462.83 Lbr: Story: 48913 PITTED CAMSHAFT LOBES AND ROLLERS FINGER ARMS. 4066750 3110 REMOVED CAMSHAFT HOUSING TO INSPECT PER 9-7010422501. FOUND PITTED CAMSHAFT LOBES AND ROLLER FINGER FOLLOWERS. DRAIN OIL AND INSPECT FILTER, OIL AND FILTER CONTAMINATED WITH METAL. OPEN CASE AND CALL TAC. TO EXPLAIN AND ASK FOR GUIDANCE WAS TOLD TO INSPECT ENGINE TO DETERMINED IF ENGINE WAS REPAIRABLE OR NOT. PULL ENGINE OUT OF TRUCK, REMOVED OIL PAN, CRANKSHAFT INSPECT BEARINGS AND CRANKSHAFT FOUND PITTED BEARINGS(MAIN AND CONNECTING RODS) CRANKSHAFT DISCOLORED AND HAVE LINE'S DEEP ENOUGH TO CATCH WITH FINGER NAILS. ENGINE BLOCK NOT COMPROMISED. REMOVED OIL PLUS AND CLEAN ENGINE BLOCK OIL PASSAGES WITH SOLVENT AND CHOP AIR. REPLACE CRANKSHAFT, INSTALLED NEW MAIN CAP BEARINGS, CONNECTING ROD BEARINGS, CAMSHAFT HOUSINGS, BOTH CAMSHAFT, BOTH CAMSHAFT ACTUATORS, ACTUATOR VALVES, ACTUATOR SOLENOIDS, HYDRAULIC LASH ADJUSTERS, OIL PAN. ALSO FOUND PITTED CHAIN GUIDES. INSTALLED NEW GUIDES, TENSIONER WITH SHOE AND ALL NECESSARY GASKETS SEALS AND BOLTS NEEDED TO COMPLETE REPAIRS. FILL WITH NEW OIL, COOLANT, BLEED COOLING SYSTEM, EVACUATE AND RECHARGE AC SYSTEM, ROAD TEST 40 MILES, INSPECT FOR ENGINE NOISE NO ABNORMAL ENGINE NOISE DUPLICATED AT THESE TIME.

Page 2, Created: 02/23/2023 05:38:28 PM

#### Case 4:23-cv-02211 Document 1-2 Filed on 06/16/23 in TXSD Page 4 of 5

## Repair Order Detail - Internal Copy

RO Number: 606649

RO Status: CLOSED

Customer: WHEELER, JAMES ROBERT

Phone(s): Contact: (903)806-7523

Vehicle: 1GCPYBEK7MZ174386

Main: (903)806-7523

2021 SILV

Silver

Click to View Cust Copy

Cell: (903)806-7523

PSX 9943

Mileage: 48,846

Service advisor: 330 Tag number: T12211

Payment type: CASH

Promised time: 03:30 PM Promised time: 03:30 PM Promised date: 11/18/2021

Waiter: No

Estimate: 0.00

Customer Comments: No

LABOR CHARGE INCLUDES R/R CRANKSHAFT, CLEAN OIL PASSAGE, FILL AND BLEED COOLING SYSTEM, EVACUATE AND RECHARGE A/C SYSTEM. EVACUATE CODE#ReHm0BhUD@00K03%pD1 RECHARGE

CODE#Qenm0BhUD@00K00*A6s

B** PARTS ONLY

> PARTS ONLY PO IC

0.00

0.00

Tech(s): 20 84578275

1 (S)BLADE 23387855 1 (S)ARM 42.98 Lbr: 0.00 Other:

0.00 Total Line B:

19.89 23.09 42.98

Pts:

Story: 48886 INSTALLED WIPER ARM AND BLADE.

Customer Pay

Labor	0.00
Parts	0.00
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	0.00
Deductible	0.00
Total Charges	0.00
Less Insurance/Adjustment	0.00
Sales Tax	0.00
Total	0.00

#### Case 4:23-cv-02211 Document 1-2 Filed on 06/16/23 in TXSD Page 5 of 5

# Repair Order Detail - Internal Copy

RO Status: CLOSED RO Number: 667530

Customer: WHEELER.JAMES ROBERT

Main: (903)806-7523

Phone(s): Contact: (903)806-7523 Vehicle: 1GCPYBEK7MZ174386

2021 SILV

Silver

Click to View Cust Copy

Cell: (903)806-7523

PSX 9943

Mileage: 78,523

Service advisor: 331 Tag number: T18123

Payment type: CC, COL, COP

Promised time: 03:30 PM

Promised date: 01/18/2023

Waiter: No

Estimate: 0.00

Customer Comments: No

Check engine light is on-report

Pts:

300 CP Check engine light is on-report

1.70

308.96

Tech(s): 36

12721653

. 50 53 1 X(S)PUMP 104.27 Lbr: 308.96 Other:

0.00 Total Line A:

104.27 413.23

Story: 170 P1467 SET IN ECM. EVAP PURGE PUMP HAS FAILED. REPLACED

EVAP PURGE PUMP

Customer Pay

Customer Fay	
Labor	308.96
Parts	104.27
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	0.00
Deductible	0.00
Total Charges	413.23
Less Insurance/Adjustment	43.36
Sales Tax	8.60
Total	378.47